



# Front Door Makeover



LEFT & ABOVE:  
Front door and surrounding wood panelling in need of maintenance. Old paint work has badly faded and is peeling and cracking. Bottom of the door frame in need of repair with bad wood taken out and filled.



LEFT:  
Years of old paint is removed using a combination of a chemical paint stripper and heat gun.  
RIGHT:  
Door and panelling is sanded down to bare wood.



LEFT:  
Knotting Agent applied to a couple of knots that still look quite resinous to avoid any possible resin bleed staining the new coating. The first coat of Protek Royal Exterior Superior Wood Finish is applied to the bare timber.



LEFT:  
Royal Exterior Somerset Blue is applied by brush to the door with China Clay in contrast on the wood pannelling & frames. Two coats produces a hard-wearing water repellent coating that allows the wood grain to show through.



LEFT:  
The transformation is complete!  
  
A faded shabby doorway is transformed in to a beautiful and elegant entrance that will look good for years.

